



Photo 1 – Aerial view of accident site



Photo 2 – Aerial view of accident site



Photo 3 – Separated wing structure



Photo 4 – Separated empennage section



Photo 5 – Left engine crater



Photo 6 – Left engine



Photo 7 – Right engine



Photo 8 – Right engine



Photo 9 – Main wreckage



Photo 10 – Cockpit engine control quadrant



Photo 11 – Right propeller



Photo 12 – Left propeller blade



Photo 13 – Left propeller blade