

CEN22FA086

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Helicopter at accident scene (NTSB Photo)



Photograph 2 - Helicopter at accident scene (NTSB Photo)



Photograph 3 - Helicopter during postaccident examination (NTSB Photo)



Photograph 4 - Engine during postaccident examination (NTSB Photo)



Photograph 5 - Transmission during postaccident examination (NTSB Photo)



Photograph 6 - Tail rotor during postaccident examination (NTSB Photo)