




Image 1 – Entire Accident Flight (Google Earth Overlay)



Image 2 – End of Accident Flight (Google Earth Overlay)




Image 3 - End of Accident Flight (Google Earth Overlay)




Image 4 - End of Accident Flight and Debris Field (Google Earth Overlay)




Photo 1 – Aerial View of the Accident Site (Source: Ohio State Highway Patrol)



Photo 2 – Right Wing (Source: NTSB)



Photo 3 - Right Elevator (Source: NTSB)



Photo 4 - Left Wing Section (Source: NTSB)



Photo 5 – Debris Field (Source: NTSB)



Photo 6 - Left Wing Strut (Source: NTSB)



Photo 7 – Left Wing and Tail (Source: NTSB)



Photo 8 – Debris Field and Initial Impact (Source: NTSB)



Photo 9 - Left Wing Section (Source: NTSB)



Photo 10 – Empennage Section (Source: NTSB)



Photo 11 – Main Wreckage (Source: NTSB)



Photo 12 - Main Wreckage (Source: NTSB)



Photo 13 – Engine and Tree Impact (Source: NTSB)



Photo 14 – Engine (Source: NTSB)



Photo 15 - Engine (Source: NTSB)



Photo 16 - Engine (Source: NTSB)



Photo 17 – Propeller Strike to Tree Branches (Source: NTSB)



Photo 18 - Propeller Strike to Tree Branch (Source: NTSB)



Photo 19 - Propeller Strike to Tree Branches (Source: NTSB)