

CEN22FA119

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of wreckage looking west (NTSB Photo)



Photograph 2 - View of wreckage looking southwest (NTSB Photo)



Photograph 3 - View of wreckage looking south (NTSB Photo)



Photograph 4 - View of wreckage looking east (NTSB Photo)



Photograph 5 - View of wreckage during examination (NTSB Photo)



Photograph 6 - View of engine during examination (NTSB Photo)