



Photo 1 – Accident Site



Photo 2 – Airplane Wreckage Forward View



Photo 3 – Airplane Wreckage Left View



Photo 4 – Airplane Wreckage Aft View



Photo 5 – Airplane Wreckage Right Side



Photo 6 - Engine



Photo 7 – Propeller and Impact Crater



Photo 8 – Propeller, Front Side View



Photo 9 – Wings Witness Marks, and Debris Field



Photo 10 – Tree Branches Impacts



Photo 11 – Approach End of Runway 17



Photo 12 – First Impact Tire Mark



Photo 13 – Tire Marks and Runway Light



Photo 14 – Broken Runway Light



Photo 15 – Tire Marks Across the Runway



Photo 16 – Tire Marks in Detail



Photo 17 – Tail Tie-down Scrape in Runway



Photo 18 – Tire Tracks off the Left Edge of the Runway