



Photo 1 – View of the accident site at the intersection, showing the wreckage near a sidewalk.



Photo 2 – View of the accident site at the intersection, showing the wreckage near a sidewalk.



Photo 3 – View of the accident site at the intersection, showing the wreckage near a sidewalk.



Photo 4 – View of the airframe at the accident site.



Photo 5 – View of the engine at the accident site.



Photo 6 – View of the wreckage layout at the salvage facility.



Photo 7 – View of the wreckage layout at the salvage facility.



Photo 8 – View of the wreckage layout at the salvage facility.



Photo 9 – View of the engine at the salvage facility.



Photo 10 – View of the propeller at the salvage facility.