



Aaron Sauer
Sr. Air Safety Investigator
Office of Aviation Safety - Central Region

Date: 06/03/2022

Subject: CEN22FA223

Contact: Witness - Hubert

According to Mr. Hubert, he was located in his residence about ½ mile from the accident site. He observed the airplane at a low altitude flying from the south to the north. The airplane then executed a right turn to the east. During the turn, the right wing dropped, and the airplane nosed down toward the terrain. He then lost sight of the airplane behind some trees and located the airplane wreckage in a field adjacent to his residence. The witness stated that he had observed the airplane performing similar flight maneuvers over the nearby fields for the past couple of weeks.