



Photo 1 – View of the bottom side of the airplane at the accident site.



Photo 2 – View of the left side of the airplane at the accident site.



Photo 3 – View of the top side of the airplane at the accident site.



Photo 4 – View of the right side of the airplane at the accident site.



Photo 5 – View of the airplane recovered from the field and placed on top of a trailer.



Photo 6 – View of the airplane laid out at the salvage facility.



Photo 7 – View of the airplane laid out at the salvage facility.



Photo 8 – View of the airplane laid out at the salvage facility.



Photo 9 – View of the airplane laid out at the salvage facility.



Photo 10 – View of the fuselage at the salvage facility.



Photo 11 – View of the bottom of the engine at the salvage facility.



Photo 12 – View of the top of the engine at the salvage facility.



Photo 13 – View of the rear of the engine at the salvage facility.



Photo 14 – View of the propeller remnants at the salvage facility.