

CEN22FA376

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Accident Site (NTSB)**




**Photograph 2 - Accident Site (NTSB)**



**Photograph 3 - Left Wing Tank (NTSB)**



**Photograph 4 - Right Wing Tank (NTSB)**



**Photograph 5 - Header Tank Contents (NTSB)**



**Photograph 6 - Gascolator Contents (NTSB)**



**Photograph 7 - Electric Fuel Pump (NTSB)**