

National Transportation Safety Board

Office of Aviation Safety
Central Region

CEN22FA405

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Site Overview



Photograph 2 - Main Wreckage at Accident Site



Photograph 3 - Left Wing



Photograph 4 - Right Wing



Photograph 5 - Engine Overview



Photograph 6 - Propeller Overview