

CEB22FA436

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Wreckage from rear right side of airplane (NTSB Photo)**



**Photograph 2 - Wreckage from rear right side of airplane (NTSB Photo)**



**Photograph 3 - Wreckage from right side of airplane (NTSB Photo)**



**Photograph 4 - Engine at wreckage location (NTSB Photo)**



**Photograph 5 - Portion of left wing in tree (NTSB Photo)**



**Photograph 6 - Engine during examination (NTSB Photo)**