



Photo 1 – Aircraft at accident site (FAA Photo)



Photo 2 – Airplane at accident site (FAA Photo)



Photo 3 – Accident propeller (Photo courtesy of American Legend Aircraft)



Photo 4 – Accident airplane with test propeller installed (Photo courtesy of American Legend Aircraft)



Photo 5 – Airplane during engine test run (Photo courtesy of American Legend Aircraft)



Photo 6 - Airplane during engine test run (Photo courtesy of American Legend Aircraft)