

CEN22LA115

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Damage Overview (Courtesy of Johnson County Airport Commission)



Photograph 2 - Fuel Servo Exam Contaminant (Courtesy of FAA)



Photograph 3 - Fuel Divider Contaminant (Courtesy of FAA)