



Photo 1: Accident Site (Source - Beegles Recovery & Storage)



Photo 2: Number 3 Cylinder Connecting Rod (Source – NTSB IIC)




Photo 3: Number 3 Cylinder Piston (Source – NTSB IIC)



Photo 4: Cylinder 5 Crankpin (Source – NTSB IIC)



Photo 5: Number 5 Cylinder Crankpin (Source – NTSB IIC)



Photo 6: Number 5 Piston Connecting Rod (Source – NTSB IIC)



Photo 7: Recovered Piston Connecting Rod End (Source – NTSB IIC)



Photo 8: Number 4 Cylinder Crankpin (Source – NTSB IIC)



Photo 9: Number 4 Cylinder Assembly (Source – NTSB IIC)



Photo 10: Number 4 Cylinder Connecting Rod (Source – NTSB IIC)



Photo 11: Oil Pan (Source – NTSB IIC)