

NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: Staunton State: IL
 ZIP: 62088 Country: United States
 Latitude: 38.77 deg North Longitude: 89.80 deg West
(Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/Time

Date: 02/20/2022 Local Time: 11:15 am
mm/dd/yyyy Time Zone: CST

Collision with Other Aircraft: ☐ Midair ☐ On-ground ☒ None

AIRCRAFT INFORMATION

Registration Number: N5042K

Manufacturer: Ryan

Model: Navion L-17 B

Serial Number: NAV-4-1654

Year of Manufacture: 1948

Amateur-Built: ☐ Yes ☒ No If Yes: ☐ Kit/Plans ☐ Original Design Make: _____

- ☐ IFR-Equipped and Certified
☐ Commercial Space Flight
☐ Unmanned Aircraft

Maximum Gross Weight: 2,801 lbs

Weight at Time of Accident/Incident: 2,700 lbs

Number of Seats: 4 Flight Crew Seats: 2

Cabin Crew Seats: _____ Passenger Seats: 1

Number of Engines: 1

Category of Aircraft

- ☒ Airplane
☐ Balloon
☐ Blimp/Dirigible
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift
☐ Rocket
☐ Ultralight
☐ Unknown

Type of Airworthiness Certificate

(Check all that apply)

- | Standard | Special |
|---|---|
| ☒ Normal | ☐ Restricted |
| ☐ Aerobatic | ☐ Limited |
| ☐ Balloon | ☐ Provisional |
| ☐ Commuter | ☐ Special Flight |
| ☐ Transport | ☐ Experimental |
| ☐ Utility | ☐ Special Light-Sport |
| | ☐ Experimental Light-Sport |
| ☐ Certificate of Authorization or Waiver (COA) | |
| ☐ None ☐ Unknown | |

Landing Gear

(Check all that apply)

- ☒ Retractable
- ☒ Tricycle ☐ Tailwheel
- ☐ Amphibian ☐ High Skid
- ☐ Emergency Float ☐ Skid
- ☐ Float ☐ Ski
- ☐ Hull ☐ Ski/Wheel
- ☐ Other Launch/Recovery System
- ☐ None ☐ Unknown

Engine Type *(Select one)*

- ☒ Reciprocating ☐ Liquid Rocket
☐ Turbo Shaft ☐ Solid Rocket
☐ Turbo Prop ☐ Hybrid Rocket
☐ Turbo Jet ☐ None
☐ Turbo Fan ☐ Unknown
☐ Electric

Fuel System Type *(Reciprocating)*

- ☐ Carburetor ☒ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Series	Manufacturer's Serial Number	Date of Mfg. <i>mm/dd/yyyy</i>	Rated Power ☒ Horsepower or ☐ lbs of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng. 1	Continental	IO/520B	126406-8-C		285	21	21	21
Eng. 2								
Eng. 3								
Eng. 4								

Last Inspection Type

- ☐ 100-Hour ☐ Continuous Airworthiness
☐ AAIP ☐ Conditional Inspection
☒ Annual ☐ Unknown

Date Last Inspection: 06012021
mm/dd/yyyy

Airframe Total Time: 3,805.02 hrs
 hours measured at *(Select one)*
☒ Last Inspection ☐ Time of Accident/Incident

Type of Maintenance Program *(Select one)*

- ☒ Annual
☐ Conditional (Amateur-built only)
☐ Manufacturer's Inspection Program
☐ Other Approved Inspection Program (AAIP)
☐ Continuous Airworthiness
☐ Other, specify: _____

Description of Fire Extinguishing System

- ☐ None
☒ Specify: Handheld

Propeller 1

- ☐ Fixed Pitch
☒ Controllable Pitch
☐ Ground Adjustable

Manufacturer: McCauley

Model: D3A32C90N

Propeller 2

- ☐ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: _____

Model: _____

ELT Installed: ☒ Yes ☐ No

If Yes:

ELT Manufacturer: _____
 Model or Part No.: _____
 TSO No.: ☐ OC91 (121.5 MHz) ☐ OC91a (121.5 MHz)
☐ OC126 (406 MHz)

Was ELT still mounted in aircraft? ☒ Yes ☐ No

Was ELT still connected to antenna? ☒ Yes ☐ No

Did ELT Activate? ☐ Yes ☒ No

If activated:

Did ELT Aid in Locating Aircraft? ☐ Yes ☐ No

If not activated:

- Indicate Reason: ☐ Impact Damage
☐ Fire Damage
☐ Battery Expired/Damaged
☒ Unknown

Additional Equipment *(Check all that apply)*

- ☒ ADS-B
☐ Airframe Parachute
☐ Angle of Attack Indicator
☐ Autopilot
☐ Data Recorder
☒ Electronic Flight Bag or Handheld Device
☐ Electronic Multifunction Display
☐ Electronic Primary Flight Display
☐ Handheld GPS
☐ Heads Up Display
☐ Onboard Weather
☒ Satellite Tracking Device
☒ Stall Warning System
☐ Video Recording Device
☐ Other, Specify: IPad Foreflight

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**Name: Albert D MeinenCity: TroyFractional Ownership Aircraft: ☐ Yes ☒ NoState: IL ZIP: 62294Country: United States**Operator of Aircraft**☒ Same As Registered Owner☒ Same Address as Registered Owner

Name: _____

City: _____

Doing Business As: _____

State: _____ ZIP: _____

Air Carrier/Operator Designator (4 Character Code): _____

Country: _____

Operating Certificates Held

(Check all that apply)

- ☐ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☐ Rotorcraft External Load (FAR 133)
☐ Commuter Air Carrier (FAR 135)
☐ On-Demand Air Taxi (FAR 135)
☐ Commercial Air Tour (FAR 136)
☐ Agricultural Aircraft (FAR 137)
☐ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☒ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☐ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437
- ☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial
- ☐ Public Aircraft (Select one)
☐ Armed Forces
☐ Federal
☐ State
☐ Local
☐ Unknown

Revenue Operation for FAR 121, 125, 129, 135

(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International
- ☐ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137

(Select one)

- ☐ Aerial Application ☐ Firefighting ☐ Unknown
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☐ Air Race/Show ☐ Instructional
☐ Banner Tow ☐ Other Work Use
☐ Business ☒ Personal
☐ Executive/Corporate ☐ Positioning
☐ External Load ☐ Skydiving
☐ Ferry

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)**

Airport Name: _____

Distance From Airport Center: _____ sm

Airport Identifier: _____

Direction From Airport: _____ degrees true

Proximity to Airport: ☐ Off Airport/Airstrip ☐ On Airport/Airstrip ☐ N/A

Airport Elevation: _____ ft. msl

Runway Information

Runway ID: _____ (L/R/C) Length: _____ ft Width: _____ ft

Runway/Landing Surface (Check all that apply)

- ☐ Asphalt ☐ Grass/Turf ☐ Macadam ☐ Water
☐ Concrete ☐ Gravel ☐ Metal/Wood
☐ Dirt ☐ Ice ☐ Snow ☐ Unknown

Condition of Runway/Landing Surface (Check all that apply)

- ☐ Dry ☐ Snow-Compacted ☐ Water-Calm
☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☐ Wet
☐ Rubber Deposits ☐ Soft
☐ Slush-Covered ☐ Vegetation ☐ Unknown

Approach/Departure Segment (Select one)

- ☐ Taxi ☐ VFR Departure ☐ On Instrument Approach ☐ Downwind ☐ Low Approach
☐ Takeoff ☐ IFR Departure Procedure/Clearance ☐ Landing ☐ Base ☐ Go Around
☐ Initial Climb ☐ Aborted Landing (after touchdown)
☐ Crosswind ☐ Unknown

IFR Approach (Check all that apply)

- ☐ None
- ☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
☐ VOR/TVOR ☐ ILS ☐ ASR
☐ VOR/DME ☐ Localizer Only ☐ Visual
☐ TACAN ☐ LOC-back course ☐ Contact
☐ RNAV ☐ Circling
☐ Unknown

VFR Approach (Check all that apply)

- ☐ None
- ☐ Traffic Pattern ☐ Stop and Go
☐ Straight-In ☐ Touch and Go
☐ Valley/Terrain Following ☐ Simulated Forced Landing
☐ Go Around ☐ Forced Landing
☐ Full Stop ☐ Precautionary Landing
☐ Unknown

[illegible]

"FLIGHT CREWMEMBER 2" INFORMATION

"Flight Crewmember 2" Responsibilities at the Time of Accident/Incident

☐ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☒ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

"Flight Crewmember 2" was pilot flying ☐ Yes ☐ No

"Flight Crewmember 2" Identification

First Name: Don

City of Residence: Edwardsville

Middle Initial: G

State: IL ZIP: 62025

Last Name: Torrini

Country: United States

Age at time of Accident/Incident: 79 Date of Birth: [REDACTED] mm/dd/yyyy

Certificate Number: [REDACTED]

Degree of Injury

☒ None
 ☐ Fatal
☐ Minor
 ☐ Unknown
☐ Serious

Seat Occupied

☐ Left
 ☐ Front
 ☐ Unknown
☒ Right
 ☐ Rear
☐ Center
 ☐ Single

Restraint Type

Available

☐ None
☒ Lap only
☐ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Used

☐ None
☒ Lap only
☐ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Inflatable Restraints

☒ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None
 ☒ Flight Instructor
 ☐ Commercial
 ☐ US Military
☐ Private
 ☐ Recreational
 ☒ Airline Transport
 ☐ Foreign
☐ Student
 ☐ Sport
 ☐ Flight Engineer

Principal Occupation

☒ Pilot
☐ Other
☐ Unknown

Medical Certificate

☐ None
 ☐ Class 3
☐ Class 1
 ☐ Driver's License (Sport Pilot only)
☐ Class 2
 ☐ Unknown

Medical Certificate Validity

☐ Without limitations/waivers
 ☐ Unknown
☐ With limitations/waivers
 ☐ N/A
☐ Special Issuance

Date of Last Medical

9/05/2018
 mm/dd/yyyy

Medical Certificate Limitations

Note: Basic Med

Medical Certificate Special Issuance

Date of Last Flight Review
 or Equivalent, Including
 FAR 121/135 Checks: 5/15/2020
 mm/dd/yyyy

Flight Review Aircraft

Make: CESSNA

Model: 150G

Airplane Rating(s) (Check all that apply)

☐ None
☒ Single-Engine Land
☐ Single-Engine Sea
☒ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s) (Check all that apply)

☐ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☒ Helicopter
☐ Powered Lift

Instrument Rating(s) (Check all that apply)

☐ None
☒ Airplane
☒ Helicopter
☐ Powered Lift

Instructor Rating(s) (Check all that apply)

☐ None
 ☒ Instrument Airplane
☒ Airplane Single-Engine
 ☒ Instrument Helicopter
☒ Airplane Multi-Engine
 ☒ Helicopter
☐ Gyroplane
 ☐ Glider
☐ Powered Lift
 ☐ Sport

Type Ratings

LR Jet, C500, SA227 and BH204

Student Endorsements (Include dates)

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	14,740	12	3,158	5,587	905	850	467	5,905		
Pilot in Command (PIC)	13,965									
Time as Instructor	6,848									
This Make/Model										
Last 90 Days	32									
Last 30 Days	12									
Last 24 Hours	0									

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information)									
Crew Name and Address					Seat Occupied		Injury		
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign					Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs						
Crew Name and Address					Seat Occupied		Injury		
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign					Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs						
PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet if necessary)									
Name and Address			Seat	Injury	Restraint Type		Inflatable Restraints	Age	
First Name: <u>Joseph</u> City : <u>St. Jacob</u> Middle Initial: _____ State: <u>IL</u> ZIP: <u>62281</u> Last Name: <u>Garrett</u> Country: <u>United States</u> ☐ Crew ☒ Passenger ☐ Other			☐ Left ☐ Center ☒ Right ☐ Unknown Row: _____	☒ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☒ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☒ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	

FLIGHT ITINERARY INFORMATION

Last Departure Point Airport ID: <u>KALN</u> City: <u>Bethalto</u> State: <u>IL</u> Country: <u>United States</u>	Time of Departure Time: <u>9:43 am</u> Time Zone: <u>CST</u>	Destination Airport ID: <u>KALN</u> City: <u>Bethalto</u> State: <u>IL</u> Country: <u>United States</u>	Type Flight Plan Filed ☒ None ☐ VFR/IFR ☐ Company VFR ☐ IFR ☐ Military VFR ☐ Unknown ☐ VFR Activated? ☐ Yes ☒ No ☐ Unknown
--	---	---	--

Type of ATC Clearance/Service (Check all that apply)

☐ None	☐ Special VFR	☐ Special IFR	☐ VFR Flight Following	☐ Cruise
☒ VFR	☐ IFR	☐ VFR On Top	☐ Traffic Advisory	☐ Unknown / NA

Airspace where the accident/incident occurred (Check all that apply)

☐ Class A ☐ Class B ☐ Class C ☐ Class D ☐ Class E	☒ Class G ☐ Demo Area ☐ Warning Area ☐ Prohibited Area ☐ Restricted Area	☐ Military Operations Area (MOA) ☐ Airport Advisory Area ☐ Jet Training Area ☐ TRSA ☐ FAR 93	☐ Special ☐ Air Traffic Control Area ☐ Unknown	Altitude of In-Flight Occurrence: <u>3,000</u> ft msl
--	--	---	---	---

WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE

Source of Pilot Weather Information

(Check all that apply)

☐ National Weather Service ☐ Flight Service Station ☐ TV/Radio ☒ Automated Report ☐ Commercial Weather Service (DUATS) ☐ On-Board Weather	☐ Company ☐ Military ☐ Internet ☐ None ☐ Unknown
---	---

Weather Observation Facility

Facility ID: KALN
 Observation Time: 9:00 AM
 Time Zone: CST
 Distance from Accident Site: 9 nm
 Direction from Accident Site: 270 degrees true

Basic Conditions

☒ VMC
☐ IMC
☐ Unknown

Light Condition

☐ Dawn ☐ Dusk ☐ Dark Night ☐ Unknown
☒ Day ☐ Night ☐ Bright Night

Sky/Lowest Cloud Condition

☒ Clear ☐ Thin Broken
☐ Few ☐ Thin Overcast
☐ Partial Obscuration ☐ Unknown
☐ Scattered

Lowest Cloud Condition Height

 ft agl

Ceiling

☒ None (Clear) ☐ Obscured
☐ Broken ☐ Indefinite
☐ Overcast ☐ Unknown

Ceiling Height

 ft agl

Temperature: (C) or 53 (F)

Dew Point: (C) or 32 (F)

Altimeter Setting: 31.8 in. Hg
or MB

Wind Direction

☐ Variable

-or-
Direction: 190 degrees true

Wind Speed

☐ Calm
☐ Light and Variable

-or-
Speed: 27 kts

Wind Gusts

☒ Not Gusting

-or-
Speed: 27 kts

Visibility 10 plus miles

RVR: feet

RVV: miles

Density Altitude: ft

Intensity of Precipitation

☐ Light
☐ Moderate
☐ Heavy
☒ N/A
☐ Unknown

Type of Precipitation (Check all that apply)

☒ None	☐ Drizzle	☐ Freezing Rain
☐ Rain	☐ Ice Pellets	☐ Snow Shower
☐ Snow	☐ Snow Pellets	☐ Ice Pellets Shower
☐ Hail	☐ Snow Grains	☐ Freezing Drizzle
☐ Rain Showers	☐ Ice Crystals	

Restriction to Visibility (Check all that apply)

☒ None	☐ Fog
☐ Blowing Dust	☐ Ground Fog
☐ Blowing Sand	☐ Haze
☐ Blowing Snow	☐ Ice Fog
☐ Blowing Spray	☐ Smoke
☐ Dust	☐ Unknown

Icing Forecast

Amount	Type
☒ None	☐ N/A
☐ Trace	☐ Rime
☐ Light	☐ Clear
☐ Moderate	☐ Mixed
☐ Severe	☐ Unknown
☐ Unknown	

Icing Actual

Amount	Type
☒ None	☐ N/A
☐ Trace	☐ Rime
☐ Light	☐ Clear
☐ Moderate	☐ Mixed
☐ Severe	☐ Unknown
☐ Unknown	

Turbulence

Type (Check all that apply)	Severity
☒ None	☐ Light
☐ Clear Air	☐ Moderate
☐ Terrain-Induced	☐ Severe
☐ Convective Turbulence	☐ Extreme

NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident:

None

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- ☐ None ☐ Substantial
☒ Minor ☐ Destroyed
 ☐ Unknown

Aircraft Fire

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Fire at Unknown Time
☐ On-Ground ☐ Unknown

Aircraft Explosion

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Explosion at Unknown Time
☐ On-Ground ☐ Unknown

Description of Damage to Aircraft and Other Property *(Use additional sheet if necessary)*

Left and Right wingtips, prop

NARRATIVE HISTORY OF FLIGHT *(Please type or print in ink)*

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

After getting ATIS at KALN; requested VFR taxi to the east. After getting clearance from tower for takeoff we requested to stay in vicinity to cycle landing gear. Was cleared for takeoff and then departed runway 17 to the east at 9:43 am. After cycling the gear we continued on to the east- climbed to 5,500 ft. to finish maneuvers including slow flight, stalls, turning stalls and standard rate turns. We then proceeded to KVL A for practice of crosswind landing. Overflew airport - right teardrop into a left downwind for runway 18. Landed runway - proceeded to apron, back taxied to runway 18 for departure. Departed runway 18 for return to KALN. Climbed to 3,000 ft. and was receiving briefing from CFI on maneuvers and landings. Appx. midway upon return to KALN noticed engine was running rough proceeded to lean to correct the problem and then noticed fuel flow gauge was pegged. Continued to attempt to lean mixture, reposition throttle, with no response. Continued to hold altitude while checking for closest airport options for landing. When it became apparent that altitude could no longer be held ;began selection of a field to execute an off airport emergency landing. Best field option was bordered on the west by large power lines and a public bike trail and to the east by rte 4.- easy access for emergency vehicles if needed.. South border - tree lines. Winds were 26 knots at 190. At this time altitude was appx. 1,500 ft. Weather conditions in the area had lead to off field being muddy. Due to power lines could not execute landing into the wind. At this time the RPM were 500-600. Motor died prior to touchdown. Landed - plane was slowed due to mud in field. After landing to the north and rolling out, crossing over a field road into next field at appx. 10 mph; the field on the other side was softer- contained more water. Right before coming to a stop the front wheel turned left in the mud- right wing hit the ground as it spun the plane around it hit the prop and the left wing before stopping pointing east. Slid the canopy back and everyone exited the aircraft with no injuries.

I do not have access to aircraft to obtain ELT info. Battery is at half life.

RECOMMENDATION (How could this accident/incident have been prevented?)

Operator/Owner Safety Recommendation

Without knowing cause of mechanical failure could not know how it could have been prevented

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)

Was there Mechanical Malfunction/Failure? ☒ Yes ☐ No
(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

Unknown

**Total Time/Cycles
On Part**

_____ Hours

_____ Cycles

**Time Since This Part
Inspected/Overhauled**

_____ Hours

FUEL & SERVICES INFORMATION

Fuel on Board at Last Takeoff
(Convert from pounds, as necessary)

31 Gallons**Fuel Type**☐ 80/87☐ 115/145☐ Jet B☐ Other, specify _____☒ 100 Low Lead☐ Jet A☐ JP8☐ 100/130☐ Jet A-1☐ Automotive**Other Services, if Any, Prior to Departure****EVACUATION OF AIRCRAFT**

Was an emergency evacuation of the aircraft performed? ☒ Yes ☐ No

Method of Exit – Describe how the occupants exited and how many occupants evacuated each location

All 3 occupants slid open canopy and exited aircraft

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for other aircraft)**Aircraft Registration Number**

Manufacturer: _____**Model:** _____**Damage to Other Aircraft**☐ Destroyed☐ Minor☐ Substantial☐ None**Registered Owner of Other Aircraft**

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

Pilot of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE

Date of this Report

02/24/2022

mm/dd/yyyy

Name of Pilot/Operator: Albert Donald Meinen

Signature: _____

-- or -- ☒ Check here to electronically sign this document

If a Person Other than Pilot/Operator is Filing Report

Name: _____

Title: _____

Signature: _____

-- or -- ☐ Check here to electronically sign this document

FOR NTSB USE ONLY

NTSB Accident/Incident No.

CEN22LA128

Reviewed by NTSB Regional Office

CEN - Central Regional Office

Name of Investigator

Michael J. Hodges

Date Report Received

02/24/2022