



Photo 1 – View of airplane from right side (FAA Photo)



Photo 2 – View of airplane from front right side (FAA Photo)



Photo 3 – View of airplane from front left side (FAA Photo)



Photo 4 – View of engine left side showing loose No. 4 rocker cover (FAA Photo)




Photo 5 – View of No. 5 rocker cover showing missing bolt (FAA Photo)




Photo 6 – View of No. 4 cylinder head (FAA Photo)



Photo 7 – Contaminated oil in rocker cover (FAA Photo)




Photo 8 – No. 4 rocker arm shaft boss (FAA Photo)