



Photo 1 – Airplane at Accident Site, Courtesy of FAA




Photo 2 – Fractured No. 1 Cylinder Shaft Rocker Bosses, Courtesy of FAA