


CEN22LA176

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Site (Sheriff's Dept Photo)



Photograph 2 - Accident Site (Insurance Adj Photo)



Photograph 3 - Accident Site (Insurance Adj Photo)



Photograph 4 - Engine / Propeller



Photograph 5 - Engine / Propeller



Photograph 6 -Engine / Propeller



Photograph 7 - Left Turbocharger Assembly



Photograph 8 - Left Turbocharger Assembly



Photograph 9 -Left Turbocharger Assembly