



Photo 1 – View of the left side of the airplane at the accident site (courtesy of the Federal Aviation Administration).



Photo 2 – View of the right side of the airplane at the accident site (courtesy of the Federal Aviation Administration).



Photo 3 – View of the engine and the propeller at the accident site (courtesy of the Federal Aviation Administration).



Photo 4 – View of the substantial damage sustained to the right wing at the accident site (courtesy of the Federal Aviation Administration).



Photo 5 – Close up view of the substantial damage sustained to the right wing at the accident site (courtesy of the Federal Aviation Administration).



Photo 6 – View of the fuel tank selector at the accident site (courtesy of the Federal Aviation Administration).