

NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: Ennis State: TX
 ZIP: 75119 Country: USA
 Latitude: 32°19' 47"N Longitude: 096°39'50"W
(Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/Time

Date: 6/2/2022 Local Time: 18:30
mm/dd/yyyy Time Zone: Central

Collision with Other Aircraft: ☐ Midair ☐ On-ground ☒ None

AIRCRAFT INFORMATION

Registration Number: N65497

Manufacturer: Cessna

Model: 172/P

Serial Number: 17275765

Year of Manufacture: 1982

Amateur-Built: ☐ Yes ☒ No If Yes: ☐ Kit/Plans ☐ Original Design Make: _____

☒ IFR-Equipped and Certified

☐ Commercial Space Flight

☐ Unmanned Aircraft

Maximum Gross Weight: 2400 lbs

Weight at Time of Accident/Incident: 2000 lbs

Number of Seats: 4 Flight Crew Seats: 2

Cabin Crew Seats: 0 Passenger Seats: 2

Number of Engines: 1

Category of Aircraft

- ☒ Airplane
☐ Balloon
☐ Blimp/Dirigible
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift
☐ Rocket
☐ Ultralight
☐ Unknown

Type of Airworthiness Certificate

(Check all that apply)

Standard

- ☒ Normal
☐ Aerobatic
☐ Balloon
☐ Commuter
☐ Transport
☐ Utility

Special

- ☐ Restricted
☐ Limited
☐ Provisional
☐ Special Flight
☐ Experimental
☐ Special Light-Sport
☐ Experimental Light-Sport

☐ Certificate of Authorization or Waiver (COA)
☐ None ☐ Unknown

Landing Gear

(Check all that apply)

☐ Retractable

- ☒ Tricycle ☐ Tailwheel
☐ Amphibian ☐ High Skid
☐ Emergency Float ☐ Skid
☐ Float ☐ Ski
☐ Hull ☐ Ski/Wheel
☐ Other Launch/Recovery System
☐ None ☐ Unknown

Engine Type *(Select one)*

- ☒ Reciprocating ☐ Liquid Rocket
☐ Turbo Shaft ☐ Solid Rocket
☐ Turbo Prop ☐ Hybrid Rocket
☐ Turbo Jet ☐ None
☐ Turbo Fan ☐ Unknown
☐ Electric

Fuel System Type *(Reciprocating)*

- ☒ Carburetor ☐ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Series	Manufacturer's Serial Number	Date of Mfg. <i>mm/dd/yyyy</i>	Rated Power ☒ Horsepower or ☐ lbs of Thrust	Total Time <i>(hours)</i>	Time Since: Inspection <i>(hours)</i>	Overhaul <i>(hours)</i>
Eng. 1	Avco Lycoming	O-360-D2J	L-10451-39A		180hp	2307.3	97	618.4
Eng. 2								
Eng. 3								
Eng. 4								

Last Inspection Type

- ☐ 100-Hour ☐ Continuous Airworthiness
☐ AAIP ☐ Conditional Inspection
☒ Annual ☐ Unknown

Date Last Inspection: 4/7/2022
mm/dd/yyyy

Airframe Total Time: 14704.6 hrs

hours measured at *(Select one)*

☐ Last Inspection ☒ Time of Accident/Incident

Type of Maintenance Program *(Select one)*

- ☒ Annual
☐ Conditional (Amateur-built only)
☐ Manufacturer's Inspection Program
☐ Other Approved Inspection Program (AAIP)
☐ Continuous Airworthiness
☐ Other, specify: _____

Description of Fire Extinguishing System

- ☐ None
☒ Specify: Portable Bottle

Propeller 1

- ☒ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: McCaughey

Model: 1C160/DTM7557

Propeller 2

- ☐ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: _____

Model: _____

ELT Installed: ☒ Yes ☐ No

If Yes:

ELT Manufacturer: _____

Model or Part No.: _____

TSO No.: ☒ C91 (121.5 MHz) ☐ C91a (121.5 MHz)
☐ C126 (406 MHz)

Was ELT still mounted in aircraft? ☒ Yes ☐ No

Was ELT still connected to antenna? ☒ Yes ☐ No

Did ELT Activate? ☐ Yes ☒ No

If activated:

Did ELT Aid in Locating Aircraft: ☐ Yes ☒ No

If not activated:

- Indicate Reason: ☐ Impact Damage
☐ Fire Damage
☐ Battery Expired/Damaged
☒ Unknown

Additional Equipment *(Check all that apply)*

- ☒ ADS-B
☐ Airframe Parachute
☐ Angle of Attack Indicator
☐ Autopilot
☐ Data Recorder
☐ Electronic Flight Bag or Handheld Device
☐ Electronic Multifunction Display
☐ Electronic Primary Flight Display
☒ Handheld GPS
☐ Heads Up Display
☐ Onboard Weather
☐ Satellite Tracking Device
☐ Stall Warning System
☐ Video Recording Device
☐ Other, Specify: _____

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**Name: Christiansen Aviation IncCity: TulsaState: OKZIP: 74132Fractional Ownership Aircraft: ☐ Yes ☒ NoCountry: United States**Operator of Aircraft**☐ Same As Registered Owner☐ Same Address as Registered OwnerName: Golf Aero Flight SchoolCity: Arlington

Doing Business As: _____

State: TXZIP: 76018

Air Carrier/Operator Designator (4 Character Code): _____

Country: United States**Operating Certificates Held**

(Check all that apply)

- ☒ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☐ Rotorcraft External Load (FAR 133)
☐ Commuter Air Carrier (FAR 135)
☐ On-Demand Air Taxi (FAR 135)
☐ Commercial Air Tour (FAR 136)
☐ Agricultural Aircraft (FAR 137)
☐ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☒ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☐ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437
- ☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial
- ☐ Public Aircraft (Select one)
☐ Armed Forces
☐ Federal
☐ State
☐ Local
☐ Unknown

Revenue Operation for FAR 121, 125, 129, 135

(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International
- ☐ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137

(Select one)

- ☐ Aerial Application ☐ Firefighting ☐ Unknown
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☐ Air Race/Show ☒ Instructional
☐ Banner Tow ☐ Other Work Use
☐ Business ☐ Personal
☐ Executive/Corporate ☐ Positioning
☐ External Load ☐ Skydiving
☐ Ferry

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION** (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)Airport Name: EnnisDistance From Airport Center: 7 smAirport Identifier: F41Direction From Airport: 150 degrees trueProximity to Airport: ☒ Off Airport/Airstrip ☐ On Airport/Airstrip ☐ N/AAirport Elevation: 500 ft. msl**Runway Information**Runway ID: 16 (L/R/C) Length: 3999 ft Width: 50 ft**Runway/Landing Surface** (Check all that apply)

- ☒ Asphalt ☐ Grass/Turf ☐ Macadam ☐ Water
☐ Concrete ☐ Gravel ☐ Metal/Wood
☐ Dirt ☐ Ice ☐ Snow ☐ Unknown

Condition of Runway/Landing Surface (Check all that apply)

- ☒ Dry ☐ Snow-Compacted ☐ Water-Calm
☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☐ Wet
☐ Rubber Deposits ☐ Soft
☐ Slush-Covered ☐ Vegetation ☐ Unknown

Approach/Departure Segment (Select one)

- ☐ Taxi ☐ VFR Departure ☐ On Instrument Approach ☐ Downwind ☐ Low Approach
☐ Takeoff ☐ IFR Departure Procedure/Clearance ☐ Landing ☐ Base ☐ Go Around
☐ Initial Climb ☐ Final ☒ Aborted Landing (after touchdown)
☐ Crosswind ☐ Unknown

IFR Approach (Check all that apply)

- ☐ None
☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
☐ VOR/TVOR ☐ ILS ☐ ASR
☒ VOR/DME ☐ Localizer Only ☐ Visual
☐ TACAN ☐ LOC-back course ☐ Contact
☐ RNAV ☒ Circling ☐ Unknown

VFR Approach (Check all that apply)

- ☐ None
☒ Traffic Pattern ☐ Stop and Go
☐ Straight-In ☐ Touch and Go
☐ Valley/Terrain Following ☐ Simulated Forced Landing
☒ Go Around ☐ Forced Landing
☐ Full Stop ☐ Precautionary Landing
☐ Unknown

"FLIGHT CREWMEMBER 1" INFORMATION

"Flight Crewmember 1" Responsibilities at the Time of Accident/Incident

☐ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☒ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

"Flight Crewmember 1" was pilot flying ☒ Yes ☐ No

"Flight Crewmember 1" Identification

First Name: Adekunle

City of Residence: Providence Village

Middle Initial: V

State: Texas ZIP: 76227

Last Name: Munis

Country: United States

Age at time of Accident/Incident: 38 Date of Birth: [REDACTED] mm/dd/yyyy

Certificate Number: [REDACTED]

Degree of Injury

☒ None
 ☐ Fatal
☐ Minor
 ☐ Unknown
☐ Serious

Seat Occupied

☐ Left
 ☐ Front
 ☐ Unknown
☒ Right
 ☐ Rear
☐ Center
 ☐ Single

Restraint Type

Available

☐ None
☐ Lap only
☒ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Used

☐ None
☐ Lap only
☒ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Inflatable Restraints

☒ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None
 ☒ Flight Instructor
 ☒ Commercial
 ☐ US Military
☐ Private
 ☐ Recreational
 ☐ Airline Transport
 ☐ Foreign
☐ Student
 ☐ Sport
 ☐ Flight Engineer

Principal Occupation

☒ Pilot
☐ Other
☐ Unknown

Medical Certificate

☐ None
 ☐ Class 3
☒ Class 1
 ☐ Driver's License (Sport Pilot only)
☐ Class 2
 ☐ Unknown

Medical Certificate Validity

☒ Without limitations/waivers
 ☐ Unknown
☐ With limitations/waivers
 ☐ N/A
☐ Special Issuance

Date of Last Medical

10/5/2021
 mm/dd/yyyy

Medical Certificate Limitations

NONE

Medical Certificate Special Issuance

N/A

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

11/19/2021
 mm/dd/yyyy

Flight Review Aircraft

Make: Piper

Model: Seminole PA-44-180

Airplane Rating(s)

(Check all that apply)
☐ None
☒ Single-Engine Land
☐ Single-Engine Sea
☒ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s)

(Check all that apply)
☒ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s)

(Check all that apply)
☐ None
☒ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s)

(Check all that apply)
☐ None
☒ Airplane Single-Engine
☒ Airplane Multi-Engine
☐ Gyroplane
☐ Powered Lift
☐ Instrument Airplane
☐ Instrument Helicopter
☐ Helicopter
☐ Glider
☐ Sport

Type Ratings

Student Endorsements (Include dates)

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	2003	569	1092	912	469	5	85			
Pilot in Command (PIC)	1883	467	1000	870	460	5	85			
Time as Instructor	1556	312	600	820	320	0	0			
This Make/Model					100	5	45			
Last 90 Days	32	20	20	0.8	0	0	0			
Last 30 Days	19	19	19	0.8	0	0	0			
Last 24 Hours	0	0	0	0	0	0	0			

"FLIGHT CREWMEMBER 2" INFORMATION

"Flight Crewmember 2" Responsibilities at the Time of Accident/Incident

☐ Pilot
 ☐ Co-Pilot
 ☒ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

"Flight Crewmember 2" was pilot flying ☐ Yes ☒ No

"Flight Crewmember 2" Identification

First Name: Luis City of Residence: Saginaw
 Middle Initial: R State: TX ZIP: 76131
 Last Name: Maldonado-Gomez Country: United States
 Age at time of Accident/Incident: 49 Date of Birth: [REDACTED] mm/dd/yyyy
 Certificate Number: [REDACTED]

Degree of Injury ☒ None ☐ Fatal ☐ Minor ☐ Unknown ☐ Serious	Seat Occupied ☒ Left ☐ Front ☐ Unknown ☐ Right ☐ Rear ☐ Center ☐ Single	Restraint Type <table style="width: 100%;"> <tr> <th style="text-align: left;">Available</th> <th style="text-align: left;">Used</th> </tr> <tr> <td> ☐ None ☐ Lap only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown </td> <td> ☐ None ☐ Lap only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown </td> </tr> </table>	Available	Used	☐ None ☐ Lap only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ None ☐ Lap only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Inflatable Restraints ☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Available	Used						
☐ None ☐ Lap only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ None ☐ Lap only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown						
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military ☒ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer		Medical Certificate Validity ☐ Without limitations/waivers ☐ Unknown ☒ With limitations/waivers ☐ N/A ☐ Special Issuance					
Principal Occupation ☐ Pilot ☒ Other ☐ Unknown	Medical Certificate ☐ None ☒ Class 3 ☐ Class 1 ☐ Driver's License (Sport Pilot only) ☐ Class 2 ☐ Unknown		Date of Last Medical <u>03/25/2021</u> mm/dd/yyyy				

Medical Certificate Limitations

Must wear corrective lenses.

Medical Certificate Special Issuance

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:
08/26/2021
 mm/dd/yyyy

Flight Review Aircraft

Make: Cessna
 Model: 150M

Airplane Rating(s) (Check all that apply) ☐ None ☒ Single-Engine Land ☐ Single-Engine Sea ☐ Multiengine Land ☐ Multiengine Sea	Other Aircraft Rating(s) (Check all that apply) ☒ None ☐ Airship ☐ Balloon ☐ Glider ☐ Gyroplane ☐ Helicopter ☐ Powered Lift	Instrument Rating(s) (Check all that apply) ☒ None ☐ Airplane ☐ Helicopter ☐ Powered Lift	Instructor Rating(s) (Check all that apply) ☒ None ☐ Airplane Single-Engine ☐ Airplane Multi-Engine ☐ Gyroplane ☐ Powered Lift ☐ Instrument Airplane ☐ Instrument Helicopter ☐ Helicopter ☐ Glider ☐ Sport
---	--	--	--

Type Ratings

Student Endorsements (Include dates)

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	194.5	40.5	194.5	0	27.7	1.2	50	0	0	0
Pilot in Command (PIC)	157.2	40.5	157.2	0	24.4	1.2	50	0	0	0
Time as Instructor	0	0	0	0	0	0	0	0	0	0
This Make/Model					6.1	1.2	29.2			
Last 90 Days	76.9	25.6	76.9	0	1.8	1.2	16	0	0	0
Last 30 Days	16.3	7.2	16.3	0	0	0	4.8	0	0	0
Last 24 Hours	1.1	1.1	1.1	0	0	0	.9	0	0	0

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information)									
Crew Name and Address					Seat Occupied		Injury		
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign					Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs						
Crew Name and Address					Seat Occupied		Injury		
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign					Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs						
PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet if necessary)									
Name and Address			Seat	Injury	Restraint Type		Inflatable Restraints	Age	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	

FLIGHT ITINERARY INFORMATION

Last Departure Point Airport ID: <u>KGKY</u> City: <u>Arlington</u> State: <u>Texas</u> Country: <u>United States</u>	Time of Departure Time: <u>17:30</u> Time Zone: <u>Central</u>	Destination Airport ID: <u>F41</u> City: <u>Ennis</u> State: <u>Texas</u> Country: <u>United States</u>	Type Flight Plan Filed ☒ None ☐ VFR/IFR ☐ Company VFR ☐ IFR ☐ Military VFR ☐ Unknown ☐ VFR Activated? ☐ Yes ☒ No ☐ Unknown
--	---	--	--

Type of ATC Clearance/Service (Check all that apply)

☐ None	☐ Special VFR	☐ Special IFR	☐ VFR Flight Following	☐ Cruise
☒ VFR	☐ IFR	☐ VFR On Top	☐ Traffic Advisory	☐ Unknown / NA

Airspace where the accident/incident occurred (Check all that apply)

☐ Class A ☐ Class B ☐ Class C ☐ Class D ☐ Class E	☒ Class G ☐ Demo Area ☐ Warning Area ☐ Prohibited Area ☐ Restricted Area	☐ Military Operations Area (MOA) ☐ Airport Advisory Area ☐ Jet Training Area ☐ TRSA ☐ FAR 93	☐ Special ☐ Air Traffic Control Area ☐ Unknown	Altitude of In-Flight Occurrence: <u>1300</u> ft msl
--	--	---	---	--

WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE

Source of Pilot Weather Information

(Check all that apply)

☐ National Weather Service ☐ Flight Service Station ☐ TV/Radio ☒ Automated Report ☐ Commercial Weather Service (DUATS) ☐ On-Board Weather	☐ Company ☐ Military ☐ Internet ☐ None ☐ Unknown
---	---

Weather Observation Facility

Facility ID: KLNC
 Observation Time: _____
 Time Zone: Central
 Distance from Accident Site: 15 nm
 Direction from Accident Site: 348 degrees true

Basic Conditions

☒ VMC
☐ IMC
☐ Unknown

Light Condition

☒ Dawn ☐ Dusk ☐ Dark Night ☐ Unknown
☐ Day ☐ Night ☐ Bright Night

Sky/Lowest Cloud Condition

☒ Clear ☐ Thin Broken
☐ Few ☐ Thin Overcast
☐ Partial Obscuration ☐ Unknown
☐ Scattered

Lowest Cloud Condition Height

_____ ft agl

Ceiling

☒ None (Clear) ☐ Obscured
☐ Broken ☐ Indefinite
☐ Overcast ☐ Unknown

Ceiling Height

_____ ft agl

Temperature: _____ (C) or _____ (F)

Dew Point: _____ (C) or _____ (F)

Altimeter Setting: _____ in. Hg
 or _____ MB

Wind Direction

☒ Variable

-or-
 Direction: _____ degrees true

Wind Speed

☒ Calm
☐ Light and Variable

-or-
 Speed: _____ kts

Wind Gusts

☒ Not Gusting

-or-
 Speed: _____ kts

Visibility 10 miles

RVR: _____ feet

RVV: _____ miles

Density Altitude: 2000 ft

Intensity of Precipitation

☐ Light
☐ Moderate
☐ Heavy
☒ N/A
☐ Unknown

Type of Precipitation (Check all that apply)

☒ None	☐ Drizzle	☐ Freezing Rain
☐ Rain	☐ Ice Pellets	☐ Snow Shower
☐ Snow	☐ Snow Pellets	☐ Ice Pellets Shower
☐ Hail	☐ Snow Grains	☐ Freezing Drizzle
☐ Rain Showers	☐ Ice Crystals	

Restriction to Visibility (Check all that apply)

☒ None	☐ Fog
☐ Blowing Dust	☐ Ground Fog
☐ Blowing Sand	☐ Haze
☐ Blowing Snow	☐ Ice Fog
☐ Blowing Spray	☐ Smoke
☐ Dust	☐ Unknown

Icing Forecast

Amount	Type
☒ None	☐ N/A
☐ Trace	☐ Rime
☐ Light	☐ Clear
☐ Moderate	☐ Mixed
☐ Severe	☐ Unknown
☐ Unknown	

Icing Actual

Amount	Type
☒ None	☐ N/A
☐ Trace	☐ Rime
☐ Light	☐ Clear
☐ Moderate	☐ Mixed
☐ Severe	☐ Unknown
☐ Unknown	

Turbulence

Type (Check all that apply)	Severity
☐ None	☐ Light
☐ Clear Air	☒ Moderate
☐ Terrain-Induced	☐ Severe
☒ Convective Turbulence	☐ Extreme

NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident:

Convective Sigment was issued for the DFW area until 4pm local time and by that time it had rained and the sky become clear.

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- ☐ None ☒ Substantial
☐ Minor ☐ Destroyed
 ☐ Unknown

Aircraft Fire

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Fire at Unknown Time
☐ On-Ground ☐ Unknown

Aircraft Explosion

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Explosion at Unknown Time
☐ On-Ground ☐ Unknown

Description of Damage to Aircraft and Other Property *(Use additional sheet if necessary)*

Right wing Clipped a tree on landing, the impact broke the right wing.

NARRATIVE HISTORY OF FLIGHT *(Please type or print in ink)*

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

We meet at Arlinton Airport KGKY to brief the days flight and talk about any contingencies, Student had flown this particular approach previously so it was just going to be a brush up flight.

The aircraft preflight was normal and fuel was 12 gallons each tank, 24 gallons total. We sumped the fuel and it looked clear blue no bubbles or dirty and smelt like AVGAS. Engine oil was a little dark and 5 quarts (I didn't think anything of it since aircraft had only 4 hours tach before 100 hours).

We did the run up and Mag drops were less than a 100rpm and carb heat showed a slight job, the Idle check did not show anything unusual. On departure we simulated the Joe Pool 5 departure Jaspa transition, he loaded the approach fine and I vectored him to intercept the Maverick VOR (TTT) to Jaspa leg. When he intercepted it without issue I told him to break off the approach and head straight to Ennis so we can setup for VOR/DME-A for F41. He loaded the approach tuned and identified the VOR and then proceeded straight to Wodie to do the procedure turn in the hold and head inbound on the approach.

It was a hot day and we were getting bounced around from the thermals real good, I also noticed a couple of time before we got to Wodie that the power dropped down to 2000rpm and I told Student to bump the power up to 2200rpm which he did. The second time when I asked him why he pulled power back he said he didn't so I told him to push the power back up to 2200rpm and this time tighten up the throttle friction lock. We were getting close to the airport and Student checked the weather for Lancaster (KLNC) as F41 had no weather reporting capability, wind was calm and the altimeter setting was in the 29.'s.

I announced our location and intentions and one other aircraft responded by saying they were holding at Wodie but would climb to 3,500ft so I told them we would descend down from 3,000ft to 2,500ft and keep an eye out for them.

I told student to descent to 2,500ft and cleared him for the approach, during the descent we came up on Wodie and I told the student in this situation it was ok to descend in the hold down to 2100ft which was the published altitude. Runway 16 is a right hand traffic runway so student descended on the approach and overflew the field to make right downwind. On the turn inbound he overshot a bit and I told him to correct towards the runway with gentle banks.

We lined up on runway 16 but the runway had no visual glide slope indicator and student landed well passed the 1000ft marker on a 4,000ft runway so I called a go around and he pushed carb heat in added full power. On takeoff the aircraft climbed for about a 100ft then it seemed to start to slow down and I asked him if we had full power and he said we did. I told him to fly the airplane and I looked down and say the rpm at 2,000 so I pulled the carb heat and no change and then leaned the mixture and enriched the mixture and the rpm did not increase. Then it dropped down to 1800rpm in which case I pushed the carb heat in and then we just stopped climbing. My next thought was to see if we could at least maintain altitude and then the rpm dropped to 1500rpm and we started to lose altitude at which point I took control and told student I was going to land on a wide road to my left as we were around 1200ft and I didn't want to turning back toward the airport and risking a low level stall. I had it set up real nice to land on the road but Student called out bridge ahead, I did think we would clear the bridge but he did not agree so I looked to the right and saw a pasture with cows grazing and I pointed the nose down and banked hard right.

The field was a good landing spot but there were about 50 cows (per the farmer) so I turned more right to avoid them, unfortunately there was a lone cow by himself once so I hit right rudder hard to avoid it and the right wing caught a tree.

It all happened so fast and I believe given the circumstance we did the best we could.

RECOMMENDATION (How could this accident/incident have been prevented?)

Operator/Owner Safety Recommendation

We should have had our own mechanics check the aircraft once it was delivered from Tulsa instead of relying on the maintenance done by the leasing company mechanics.

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)Was there Mechanical Malfunction/Failure? ☒ Yes ☐ No

(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

The engine RPM started to drop and Carb heat and leaning and enriching the mixture did not seem to fix the problem.

Total Time/Cycles
On Part2307.3 Hours

____ Cycles

Time Since This Part
Inspected/Overhauled97 Hours**FUEL & SERVICES INFORMATION**

Fuel on Board at Last Takeoff

(Convert from pounds, as necessary)

24 Gallons

Fuel Type

☐ 80/87☐ 115/145☐ Jet B☐ Other, specify _____☒ 100 Low Lead☐ Jet A☐ JP8☐ 100/130☐ Jet A-1☐ Automotive

Other Services, if Any, Prior to Departure

None

EVACUATION OF AIRCRAFTWas an emergency evacuation of the aircraft performed? ☐ Yes ☒ No

Method of Exit – Describe how the occupants exited and how many occupants evacuated each location

We opened the left hand side door and came out.

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for other aircraft)

Aircraft Registration Number

Manufacturer: _____

Model: _____

Damage to Other Aircraft

☐ Destroyed☐ Minor☐ Substantial☐ None

Registered Owner of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

Pilot of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE

Date of this Report

6/7/2022

mm/dd/yyyy

Name of Pilot/Operator: Adekunle Victor Munis

Signature: _____

-- or --

☐

Check here to electronically sign this document

If a Person Other than Pilot/Operator is Filing Report

Name: _____

Title: _____

Signature: _____

-- or --

☐

Check here to electronically sign this document

FOR NTSB USE ONLY

NTSB Accident/Incident No.
CEN22LA230

Reviewed by NTSB Regional Office
Central

Name of Investigator
Folkerts

Date Report Received
6/7/2022