

Carburetor Icing Probability Graph – CEN22LA230

Airplane: Cessna 172P

Accident Date: 06/02/2022

Accident Location: Ennis, TX

Accident Time: 1803 CDT

Weather: KJWY 022255Z AUTO 36006KT 10SM CLR 29/17
A2995

Celsius to Fahrenheit Conversion:

Temperature, 29° C = 84.2° F

Dew Point, 17° C = 62.6° F

Source: Federal Aviation Administration

Special Airworthiness Information Bulletin CE-09-35

Carburetor Icing Prevention

