



Photo 1: Aircraft Wreckage of N9087S (Source – Federal Aviation Administration)



Photo 2: Left Side Engine Cowl (Source – Federal Aviation Administration)



Photo 3: Fuel Control Assembly (Source – NTSB IIC)



Photo 4: Fuel Control Assembly Control Arm Shaft (Source – NTSB IIC)