



Photo 1 – Front View of Airplane, Courtesy of FAA



Photo 2 – Fire Damaged Cockpit, Courtesy of FAA



Photo 3 – Exhaust Components at Initial Exam, Courtesy of FAA




Photo 4 – Closer View of Exhaust Components at Initial Exam, Courtesy of FAA