



Photo 1 – View of the airplane on the runway (courtesy of the Federal Aviation Administration).



Photo 2 – View of the airplane on the runway (courtesy of the Federal Aviation Administration).



Photo 3 – View of the cockpit after the airplane came to rest on the runway (courtesy of the Federal Aviation Administration).



Photo 4 – View of the underside of the fuselage, showing the substantial damage (courtesy of the Federal Aviation Administration).



Photo 5 – View of the left side main landing gear (courtesy of the Federal Aviation Administration).



Photo 6 – View of the nose main landing gear (courtesy of the Federal Aviation Administration).



Photo 7 – View of the right side main landing gear (courtesy of the Federal Aviation Administration).