



Photo 1 – Front view of the airplane (courtesy of the Federal Aviation Administration).




Photo 2 – View of the damage sustained to the firewall (courtesy of the Federal Aviation Administration).



Photo 3 – View of the damage sustained to the underside of the fuselage (courtesy of the Federal Aviation Administration).