



Photo 1 – Helicopter at accident site (Photo courtesy of FAA)



Photo 2 – Helicopter aft fuselage (Photo courtesy of FAA)



Photo 3 – Damage to tail boom (Photo courtesy of FAA)



Photo 4 – Helicopter fuel gauge during examination by FAA (Photo courtesy of FAA)