



Photo 1 – View of the left side of the airplane at the accident site (courtesy of the Federal Aviation Administration).



Photo 2 – View of the left side of the airplane at the accident site (courtesy of the Federal Aviation Administration).



Photo 3 – View of the right side of the airplane at the accident site (courtesy of the Federal Aviation Administration).



Photo 4 – View of the right side of the airplane at the accident site (courtesy of the Federal Aviation Administration).



Photo 5 – View of the top of the cockpit (courtesy of the Federal Aviation Administration).



Photo 6 – View of the left side of the cockpit (courtesy of the Federal Aviation Administration).



Photo 7 – View of the right side of the cockpit (courtesy of the Federal Aviation Administration).



Photo 8 – View of the two Bose A20 aviation headsets (courtesy of the Federal Aviation Administration).



Photo 9 – View of the left side of the airplane at the salvage facility.



Photo 10 – View of the right side of the airplane at the salvage facility.



Photo 11 – View of the rear of the airplane at the salvage facility.




Photo 12 – View of the cockpit area.



Photo 13 – View of the front of the engine.



Photo 14 – View of the left side of the engine.



Photo 15 – View of the rear of the engine.



Photo 16 – View of the right side of the engine.




Photo 17 – View of the propeller.



Photo 18 – Overall view of the wreckage laid out.



Photo 19 – Overall view of the wreckage laid out.



Photo 20 – Overall view of the wreckage laid out.