



Photo 1 – View of the front of the airplane at the accident site (courtesy of the Federal Aviation Administration).



Photo 2 – View of the left side of the airplane at the accident site (courtesy of the Federal Aviation Administration).



Photo 3 – View of the right side of the airplane at the accident site (courtesy of the Federal Aviation Administration).



Photo 4 – View of the rear of the airplane at the accident site (courtesy of the Federal Aviation Administration).



Photo 5 – View of the propeller and the engine at the accident site (courtesy of the Federal Aviation Administration).



Photo 6 – View of the right wing at the accident site (courtesy of the Federal Aviation Administration).