



Photo 1 – Accident Site (Courtesy of KEOS Airport Manager)



Photo 2 - Ring Wing Damage (Courtesy of KEOS Airport Manager)



Photo 3 - Ring Wing Damage (Courtesy of KEOS Airport Manager)



Photo 4 - Left Wing Damage (Courtesy of KEOS Airport Manager)



Photo 5 – Ring Wing Damage (Courtesy of KEOS Airport Manager)