



Photo 1 – Airplane with Bent Propeller and Collapsed Nose Gear (Provided by FAA)



Photo 2 – Wrinkled Floor of Airplane (Provided by FAA)