



Photo 1 – Damage to the main landing gear – Courtesy of FAA (Federal Aviation Administration)



Photo 2 – Fuselage Damage to the right side – Courtesy of FAA