

CEN22LA386

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Propeller Damage (Courtesy of FAA)



Photograph 2 - Right Wing Damage (Courtesy of FAA)



Photograph 3 - Registration Number (Courtesy of FAA)



Photograph 4 - Float Damage (Courtesy of FAA)



Photograph 5 - Left Float Damage (Courtesy of FAA)



Photograph 6 - Right Wing Outboard Damage (Courtesy of FAA)