



Photo 1 – Airplane Wreckage in Hangar after Recovery (Source FAA)



Photo 2 – Closeup of Substantial Damage to Left Wing