

National Transportation Safety Board

Office of Aviation Safety
Central Region

CEN22LA440

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane at Accident Site, Left Side (Courtesy of Airplane Owner)



Photograph 2 - Airplane at Accident Site, Right Side (Courtesy of Airplane Owner)



Photograph 3 - Airplane at Accident Site, Front (Courtesy of Airplane Owner)



Photograph 4 - Left Wing Damage (Courtesy of Airplane Owner)



Photograph 5 - Airplane at Accident Site, Left Side (Courtesy of FAA)



Photograph 6 - Airplane at Accident Site, Rear (Courtesy of FAA)



Photograph 7 - Aft Fuselage Damage (Courtesy of FAA)



Photograph 8 - Damage to Left Side of the Stabilator (Courtesy of FAA)