

CEN23FA038

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Site



Photograph 2 - Accident Site



Photograph 3 - Left Outboard Wing



Photograph 4 - Accident Site



Photograph 5 - Accident Site



Photograph 6 - Left Engine / Propeller



Photograph 7 - Left Engine / Propeller



Photograph 8 -Right Engine / Propeller



Photograph 9 - Right Engine



Photograph 10 - Cockpit Fuel Selectors