

CEN23FA060

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Overall view of the accident site. (NTSB Photo)



Photograph 2 - Airplane from left rear. (NTSB Photo)



Photograph 3 - Airplane from left front. (NTSB Photo)



Photograph 4 - Airplane from front. (NTSB Photo)



Photograph 5 - Accident airplane engine during examination (NTSB Photo)



Photograph 6 - Aircraft magnetos during engine examination (NTSB Photo)



Photograph 7 - Fire damaged left magneto (NTSB Photo)