

CEN23FA095

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Overall view of accident scene (NTSB Photo)



Photograph 2 - View of airplane from front right (NTSB Photo)



Photograph 3 - View of airplane from front (NTSB Photo)



Photograph 4 - View of airplane from left side (NTSB Photo)



Photograph 5 - View of airplane from left rear (NTSB Photo)



Photograph 6 - View of airplane from rear (NTSB Photo)



Photograph 7 - View of airplane from right rear (NTSB Photo)



Photograph 8 - View of right stabilizer and elevator (NTSB Photo)



Photograph 9 - View of left stabilizer and elevator (NTSB Photo)



Photograph 10 - View of vertical stabilizer and rudder (NTSB Photo)



Photograph 11 - View of the airplane's engine and propeller (NTSB Photo)