

CEN23FA155

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane Wreckage at Accident Site

Date & Time: Fri, Apr 14, 2023 at 13:31:30 CDT
Position: +036.387068° / -091.489419° (± 15.5 ft)
Altitude: 496ft (± 11.1 ft)
Datum: WGS-84
Azimuth/Bearing: 251° S71W 4462mils True ($\pm 12^\circ$)
Elevation Angle: -03.2°
Horizon Angle: $+00.6^\circ$
Zoom: 1.0X



Photograph 2 - Closeup of Airplane Wreckage at Accident Site