

CEN23FA167

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Airplane Overview (Courtesy of NTSB)



Photograph 2 - Accident Airplane Overview (Courtesy of NTSB)



Photograph 3 - Separated Left Wing after Recovery (Courtesy of NTSB)



Photograph 4 - Engine & Propeller (Courtesy of NTSB)