

CEN23FA174

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Site



Photograph 2 - Accident Site



Photograph 3 - Main Wreckage



Photograph 4 - Main Wreckage



Photograph 5 - Right Wing



Photograph 6 - Right Wing (Sheriff's Office Photo)



Photograph 7 - Engine