

Alexander Lemishko
Senior Air Safety Investigator
NTSB, Central Region

Date: May 14, 2023

Subject: Memorandum for the Record CEN23FA187
Security Camera Footage

Contacts: Alexander Lemishko - NTSB IIC

A security camera was located about 1.5 miles from the accident site. The camera showed what seemed to be the accident airplane's landing light. The light gradually descended toward the ground until it disappeared. The footage showed precipitation and fog.

Alexander Lemishko



NTSB Senior Air Safety Investigator
Denver, Colorado