

CEN23FA248

INVESTIGATION PHOTOGRAPHS/IMAGES




Image 1 - Accident Flight Track on Google Earth




Image 2 - End of Accident Flight Track on Google Earth




Image 3 - End of Accident Flight Track on Google Earth




Image 4 - End of Accident Flight Track on Google Earth



Photograph 1 - Aerial View of Accident Area (Courtesy of Sheriff's Office)



Photograph 2 - Aerial View of Accident Site (Courtesy of Sheriff's Office)



Photograph 3 - Aerial View of Accident Site (Courtesy of Sheriff's Office)



Photograph 4 - Front View of Accident Airplane (Courtesy of Sheriff's Office)



Photograph 5 - Right View of Accident Airplane (Courtesy of Sheriff's Office)



Photograph 6 - Left View of Accident Airplane (Courtesy of Sheriff's Office)



Photograph 7 - Right Wing Damage (Courtesy of NTSB)



Photograph 8 - Engine and Propeller (Courtesy of NTSB)



Photograph 9 - Propeller Damage (Courtesy of NTSB)