



Jason Aguilera
Senior Air Safety Investigator
Aviation Safety - Central Region

Date: July 31, 2023

Subject: CEN23FA340

Contact: Mary Ann Williams

Mary Ann Williams lives near the accident site (about 1.4 miles west) and was working outside when the helicopter was spraying the field. She had seen the helicopter and heard helicopter's engine, which sounded normal until she didn't hear the helicopter. She looked over towards the field and saw a plume of dust.

---END---