

CEN23FA340

INVESTIGATION PHOTOGRAPHS




Photograph 1 - Main Wreckage




Photograph 2 - Main Rotor Hub




Photograph 3 - Tailboom Section



Photograph 4 - AgNav Side View



Photograph 5 - Garmin Data



Photograph 6 - Power Line Pole