

CEN23FA353

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Left side of airplane at accident site (Source: NTSB)



Photograph 2 - Front left side of airplane at accident site (Source: NTSB)



Photograph 3 - Right side of airplane at accident site (Source: Air tractor)



Photograph 4 - Front right side of airplane at accident site (Source: NTSB)