

CEN23FA359

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Side View




Photograph 2 - Accident From Airplane Tail



Photograph 3 - Canopy Pin Blocks



Photograph 4 - Canopy Side Pins (Courtesy of Van's Aircraft)



Photograph 5 - Canopy Side Pin Guides (Courtesy of Van's Aircraft)



Photograph 6 - AA Battery