

CEN23FA361

INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Still image of ejection from YouTube video at https://youtu.be/U6_kC1ntIng
(Courtesy of KMPH TV)**



Photograph 2 - Main wreckage site (NTSB Photo)



Photograph 3 - Main wreckage (NTSB Photo)



Photograph 4 - Front of main wreckage (NTSB Photo)



Photograph 5 - Front of engine (NTSB Photo)



Photograph 6 - Bottom of main wreckage (NTSB Photo)



Photograph 7 - Main wreckage (NTSB Photo)