

CEN23FA391

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Fuselage



Photograph 2 - Empennage, Retractable Propeller and Engine Radiator



Photograph 3 - Propeller in Nonstandard Position



Photograph 4 - Shoulder Harness



Photograph 5 - Right Side Lap Seatbelt



Photograph 6 - Engine Cockpit Controls



Photograph 7 - Flap Lever in Landing Position