



Photo 1 – Accident airplane (Source: Federal Aviation Administration)



Photo 2 – Left side of engine (Source: Lycoming Engines)



Photo 3 – Right side of engine (Source: Lycoming Engines)




Photo 4 – Rear side of engine (Source: Lycoming Engines)



Photo 5 – Fuel injector servo inlet (Source: Lycoming Engines)