



Photo 1 – Runway impact and propeller strikes (Source: Federal Aviation Administration)



Photo 2 – Accident airplane (Source: Federal Aviation Administration)



Photo 3 – Fractured empennage structure (Source: Federal Aviation Administration)



Photo 4 – Damaged rudder (Source: Federal Aviation Administration)